### **Schedule of Accreditation**

issued by

# United Kingdom Accreditation Service 2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

0170

Type C

Assessment Manager: MS5 Page 1 of 4



0170 Type C Inspection Body

Accredited to ISO/IEC 17020:2012

## Schedule of Accreditation issued by

United Kingdom Accreditation Service
2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

#### **Element Materials Technology Environmental UK Limited**

Issue No: 028 Issue date: 02 November 2020

Inspection performed by the Organisation at/from the locations specified

Location details		Activity	Location code
Address Element Materials Technology Environmental UK Limited Oldbury Power Station Oldbury Naite Thornbury BS35 1RQ	Local contact Mr Abdul Selemani Tel: +44 (0)1454 893539 Email: abdul.selemani@element.com	Asbestos: Surveying	Ob
Address Element Materials Technology Environmental UK Limited Trawsfynydd Power Station Blaenau Ffestiniog Gwynedd Wales LL41 4DT United Kingdom	Local contact Mr David Howarth Tel: +44 (0)1766 543548 Email: david.howarth@element.com	Asbestos: Surveying	Tf
Address  Element Materials Technology Environmental UK Limited  Wylfa Power Station Cemaes Bay LL67 0DH  Local contact  Mr Andrew Glover Tel: +44 (0) 7472 877386 Email: andrew.glover@exova.com		Asbestos: Surveying	Wf
ddress  lement Materials Technology nvironmental UK Limited erkeley Power Station erkeley 13 9PA  Local contact Mr David Rolfe Tel: +44 (0)7921 511417 Email: david.rolfe@element.com		Asbestos: Surveying	Bk

#### Address

Element Materials Technology Environmental UK Limited Dungeness A Power Station

Assessment Manager: MS5 Page 2 of 4



0170 Type C Inspection Body

Accredited to ISO/IEC 17020:2012

### Schedule of Accreditation issued by

United Kingdom Accreditation Service
2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

#### **Element Materials Technology Environmental UK Limited**

Issue No: 028 Issue date: 02 November 2020

Inspection performed by the Organisation at/from the locations specified

#### **DETAIL OF ACCREDITATION**

Field of Inspection

Type and Range of Inspection

Methods and Procedures

Location

Code

Assessment Manager: MS5 Page 4 of 4